


<b>CITY OF BALTIMORE WET WEATHER CONSENT DECREE SMOKE AND DYED WATER TESTING FORM</b>		Page 1 of 3
Sewershed: Low Level Subsewershed: 44	Company: REI/DRAYCO	Date: 08/27/2008
Test Type: Smoke	Ground Condition: Dry: X Damp: _ Wet: _	Supervisor: E.R. Crew: 04
Manhole ID: S19M__035MH	Test ID: 1029-576	Notifications Made: __X__ Residents, Fire, 311
Field Sketch: (Show all manholes with numbers, blower placement location, sandbag or isolation locations, street names, building addresses and locations, defect locations and photograph numbers)		

BLOWER #1  
S19M\_\_035MH

576\_OB01-01



[illegible]

**CITY OF BALTIMORE**  
**SMOKE TESTING OBSERVATION SUMMARY**  
**LOW LEVEL SEWERSHED**  
BALTIMORE CITY PROJECT 1029  
REI/DRAYCO

Unique Test ID: 576	Date: 08/27/2008	Basin: LL - 44	Manhole ID: S19M__035MH
Defect No: OB01	Supervisor: E.R.	Crew: 04	Dye Test Recommended: N
Location: 403 S. FURROW ST.			
Source Type: 09 Building Interior		Sector: 02 Private	
Location: 14 Other		Severity: 03 Moderate	
Comments: SMOKE COMING FROM INTERIOR OF BUILDING.		Drainage Area: 0	

SMOKE TEST PHOTOGRAPHS



Photograph No: OB01-01  
Filename: 1029-576\_OB01-01.jpg